Message Text

UNCLASSIFIED

PAGE 01 TANGIE 00262 221548Z ACTION NEA-11

INFO OCT-01 ISO-00 ICAE-00 FBOE-00 A-01 /013 W

-----078615 221553Z/50

P R 221400Z MAY 78 FM AMCONSUL TANGIER TO SECSTATE WASHDC PRIORITY 3963 INFO AMEMBASSY RABAT

UNCLAS TANGIER 0262

E.O. 11652: N/A TAGSBC SCUL, MO SUBL TALMS

REF.: STATE 128405 (NOTAL)

- 1. ROOM IN WHICH NEW WALL TO BE CONTRUCTED IS ON GROUND FLOOR OF MOORISH PAVILLION. AS DIXON WILL RECALL THE GROUND FLOOR OF THIS BE LDING CONSISTS OF ONE LARGE ROOM WHICH DITOMMASO HAS BEEN USING AS AN OFFICE, A SMALL ROOM TO THE REAR SEPARATED BY ARCHES FROM THE LARGE OOM, AND A THIRD ROOM TO THE SIDE WHICH WAS CONVERTED INTO A KITCHEN SOME YEARS AGO. IT IS THE SMALL ROOM TO THE REAR THAT WE WISH TOUSE AS A LIBRARY. THE BACK AND SIDE WALLS ARE SO DAMP, HOWEVER THAT THE ROOM CANNOT BE USED IN ITS PRESENT CONDITION FOR A LIBRARY OR FOR ANY OTHER PURPOSE.
- 2. I FAIL TO SEE WHY FBO APPROVAL IS NECESSARY. THIS IS
 ONLY A REPAIR JOB NOT A STRUCTURAL ALTERATION. NEW WALLS WILL
 BE PUT UP ABOUT SIX INCHES INSIDE THE PRESENT WALLSTO ACT
 AS A DAMPNESS BARRIER, BUT THERE WILL BE NO ALTERATION
 WHATSOEVER TO THE PRESENT WALLS. IN EFFECT WHAT WE
 PROPOSE DOING IS COMPARABLE TO RESURFACING A ROOF TERRACE.
 IF WE WERE GOING TO REMOVE ORALTER THE EXISISTING WALLS,
 FBO APPROVAL WOULD OF COURSE BE NECESSARY BUT THAT IS NOT
 THE CASE. THE ERECTION OF THE DAMPNESS BARRIER IN MY VIEW
 UNCLASSIFIED

UNCLASSIFIED

PAGE 02 TANGIE 00262 221548Z

CLEARLY COMES WITHIN THE REPAIR AND MAINTENANCE OBLIGATION TALMS ASSUMED UNDER ITS CONTRACT WITH FBO.

 ${\tt 3.}\ \ {\tt REQUEST}\ {\tt TELEGRAPHIC}\ {\tt APPROVAL}\ {\tt ASAP.EASTMAN}$

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: Z Capture Date: 01 jan 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 22 may 1978 Decaption Date: 20 Mar 2014
Decaption Note: 25 YEAR REVIEW Disposition Action: n/a Disposition Approved on Date: Disposition Case Number: n/a Disposition Comment: Disposition Date: 01 jan 1960 Disposition Event:

Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978TANGIE00262
Document Source: COR **Document Unique ID: 00**

Drafter: n/a Enclosure: n/a Executive Order: N/A

Errors: N/A **Expiration:**

Film Number: D780215-0711

Format: TEL From: TANGIER **Handling Restrictions:**

Image Path: ISecure: 1

Legacy Key: link1978/newtext/t19780532/aaaabany.tel

Line Count: 59 Litigation Code IDs: Litigation Codes:

Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM

Message ID: b9aa0799-c288-dd11-92da-001cc4696bcc

Office: ACTION NEA

Original Classification: UNCLASSIFIED
Original Handling Restrictions: ONLY
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a

Page Count: 2
Previous Channel Indicators: n/a Previous Classification: n/a
Previous Handling Restrictions: ONLY

Reference: 78 STĂTE 128405

Retention: 0

Review Action: RELEASED, APPROVED Review Content Flags:

Review Date: 29 mar 2005 Review Event: Review Exemptions: n/a **Review Media Identifier:** Review Release Date: N/A Review Release Event: n/a **Review Transfer Date:**

SAS ID: 2611970 Secure: OPEN Status: NATIVE Subject: TALMS TAGS: SCUL, ABLD, BC, MO

Review Withdrawn Fields: n/a

To: STATE Type: TE

vdkvgwkey: odbc://SAS/SAS.dbo.SAS_Docs/b9aa0799-c288-dd11-92da-001cc4696bcc

Review Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014

Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014